



KLUŚ Inspiring Solutions

Canopy BOX-K600











1. Profile BOX-K
2. Fastener FI-8-LIN-BOX-Z
3. Cable gland M10
4. Electric cubes
5. Wire 5 x 0,75 mm²
6. Ground wire with power connector M3


IMPORTANT: Not all possible mounting procedures are presented here.
More mounting procedures and related accessories can be found at www.KlusDesign.eu.
Drawings in these instructions are simplified and only approximate the actual shapes.


3
13
23




Version with one fastener FI-8, powered by wire


Ia




IIa




IIIa




IVa




Va




VIa




VIIa




VIIIa




IXa




Xa



XIa





XIIa




X


Canopy demontage






XIVa







XVa




XVIa




XVIIa






Version with two fasteners FI-8, powered by wire


Ib




IIb




IIIb




IVb




Vb




VIb




VIIb




VIIIb




IXb




Xb




XIb




XIIb



XIIIb





XIVb




XVb


Canopy demontage






XVIb







XVIIb




XVIIIb






Version with two fasteners FI-8, powered by steel wires CU


Ic




IIc




IIIc




IVc




Vc




VIc




VIIc




VIIIc




IXc




Xc




XIc




XIIc




XIIIc



XIVc





XVc




XVIc

Canopy demontage







XVIIc



XVIIIc



XIXc



XXc

